


Closure proposal of sand sairat sources from District Survey Report

SI No	Name of the Tahasil	Name of the Sairat	Mouza	Khata No	Plot no	Area	Kisam	Remarks
1	Banki	Ramchandrapur Morrur Quarry	Ramchandrapur	451	1031 1030	Ac 19.16 Ac 5.34	Patharbani	There are so many numbers of trees growth in the proposed area and morrum is not good quality .
2		Dengamba Morrur Quarry	Dengamba	566	887	Ac 13.14	Mundia	There are so many number of trees grows in the proposed area and the said land is handed over to Dengamba Village committee for forest afforestation and morrum is not good quality.
3	Nischintakolli	Gholapur Stone Quarry	Gholapur	814	594	Ac 5.00	Pahad	There is tree growth in the proposed area and quality of material is very bad. Joint and cracks are found every where.
4		Chitroptala R/S Sanaroutpati	Sanaroutpati	49	185	Ac.12.355	Nadi	The total lease area of the source is covered with the river water. The source has lost its feasibility & geographical character.


 Deputy Collector, Touzi & Loans,
 Collectorate, Cuttack