


Closure proposal of sand sairat sources from District Survey Report

SI No	Name of the Tahasil	Name of the Sairat	Mouza	Khata No	Plot no	Area	Kisam	Remarks
1	Kantapada	Simalada Devi River Sand	Simalada	218	26(P)	Ac. 12.20	Nadi	The Joint enquiry was made on Dt. 14.1.2022 by the committee consisted with Tahasildar Kantapada, Addl Tahasildar, Kantapada, Geologist, Cuttack, Mining Officer, Cuttack Asst. Executive Engineer Irrigation, Pratapnagari, R.S Kantapada & R.I Govindpur and Amin who have suggested that the source do not contain adequate amount of sand (approximately 5% of the total minable area with 0.5 metre depth of sand deposition) and rest part is water logged covered with grass and common reeds. The source boundary is only a distance of 300 metres from the nearest source Sirasundarpur which is not feasible as per OMMC Rule. Due to meandering of the river channel, embankment is not safe during flood situation. The team recommended for closure of the source. A spot field visit was also made on Dt. 23.11.2022 by Sub-Collector, Sadar, Cuttack along with Tahasildar, Kantapada and also agreed with the joint enquiry report and suggested to close the source.


 Deputy Collector (Touzi & Loans),
 Collectorate, Cuttack